*The 1st International Conference on Business and Engineering Management (IConBEM 2020)* February 1st 2020, Institut Teknologi Sepuluh Nopember, Surabaya, Indonesia

# Lean Manufacturing Approach to Improve Speaker Manufacturing Process

Nastiti Puji Lestari<sup>1</sup> and Putu Dana Karningsih<sup>2</sup>

<sup>1</sup>Department of Technology Management, Institut Teknologi Sepuluh Nopember, Surabaya <sup>2</sup>Department of Industrial Engineering, nstitut Teknologi Sepuluh Nopember, Surabaya *e-mail*: lestari.nastitipuji@gmail.com

Abstract-PT Y is a subsidiary of Y Group which specializes in producing speakers for local and international markets. At present PT Y's orders have not met the expected performance targets. Fulfillment of production orders reached 97.55% of the target of 100%. This is one of the concern of Y Group that PT Y need to improve themselves because it can result in companies becoming less competitive than competitors. Based on preliminary observations, there was indications of waste, namely defects, downtime, and process delays. The lean tool used for further waste analysis is Lean Assessment Matrix (LAM). The results of the research show that the waste which gives the most significant influences are transportation, waiting and inventory. The root causes of problems between work stations are not ergonomic, do not have preventative maintenance schedules, there are no standards for handling defective products, the layout of the room is not in the direction of material, the carrying capacity of hand trucks is small, and the Outgoing Quantity Check (OQC) processes are not included in the company's time standards. The proposed improvement recommendations include conducting training to improve product repair skills, relayout of production plant, and making a preventative machine maintenance schedule.

*Keywords*—Lean Assessment Matrix, Lean Manufacturing, Process Activity Mapping, Value Stream Mapping, Waste Elimination.

#### I. INTRODUCTION

**P**T. Y is a subsidiary of Group Y which specialize in producing speakers for local and international market. Speaker products fall into the category of audio equipment consisting of three groups, namely Audio Visual Products (AV) for customers (customers), Professional Audio Equipment (PA) for the music industry and music activists, and Information and Communication Technology Devices (ICT) such as networks voice-based communication devices and equipment.

PT Y has a policy in determining reasonable overtime (forecast overtime) based on the availability of labor at a certain time based on the availability of labor and the level of demand for the company's products. In 2018, the actual overtime of PT Y is higher than the forecast overtime. Based on Figure 1, it is known that the actual overtime of PT Y generally fluctuates with the tendency of actual overtime to be higher than the forecast overtime.

The production process at PT Y is carried out in several parts of Wood Working (WW), Speaker Processing Unit (SPU), Painting, Printed Circuit Board (PCB), Rear Panel Assembly (RPA), and Sub-Assembly (SA) before being assembly as the final product in Final Assembly (FA). For the production process in the FA section to run smoothly, the input from the process in the previous section must run




Figure 1. Overtime Production Department in 2018.

smoothly and without delay. The biggest cause of loss time in the FA process is the PCB section of 198.88 hours per year, followed by the PTG section 124.97 hours per year, and the WW section 120.93 hours per year.

The PCB process is the process of making electrical components used in speakers. Some of the processes carried out in the PCB section include the Surface Mount Technology (SMT) process, the Auto Insert (AI) process, and the Manual Insert (MI) process. In the SMT and AI process is carried out using a production machine, while in the MI process is carried out by the operator manually (by using a production tool). The initial process of the series of production processes in the PCB section is the SMT process. In the SMT process there are two production lines that support the entire production process at PT Y. In 2018, the average downtime on SMT line 1 is 19.11% and SMT line 2 is 21, 00%. This level of downtime does not meet the standards of the Japanese Institute of Plant Maintenance (JIPM) which states that the acceptable value of downtime is  $\leq 10\%$  [1].

In PCB MI process, the problems faced include defect which causes the production process to not run smoothly because it has to go through a rework and repair process. As a percentage, the number of defects in the PCB section is very low with a percentage of less than one percent of production output. However, the percentage of electric NG to overall NG is quite large with a range between 16.89% to 36.20%. Electrical NG is the functional defect of components caused by process or material errors that cannot be identified only from the appearance of PCB. If there is an electrical NG, Production Engineering Department (PE-Repairmen) needs to do an analysis of the NG. The average analysis until it can be decided whether the PCB can be repaired (OK), Not Good (NG), Scrap (discarded), or EXPE (further PE-Repairmen analysis) is 3 days with an analysis deadline of two weeks. This is very detrimental considering the company uses a weekly shipping policy (weekly shipping) in shipping finished products. These waste cause the total fulfillment of

### The 1<sup>st</sup> International Conference on Business and Engineering Management (IConBEM 2020) February 1<sup>st</sup> 2020, Institut Teknologi Sepuluh Nopember, Surabaya, Indonesia




 Table 3.

 Activities in Speaker Production Process in PCB Section

Activity	Total	Time (sec)	Percentage
VA	21	1592,58	20%
NVA	34	78715,71	33%
NNVA	48	29712,73	47%
Total	103	110021,02	100%
ctivities in Speal	Tabl ker Production		Section by Typ
Activity	Total	Time (sec)	Percentage
0	60	23.621,92	58%
Т	15	25.667,67	15%
Ι	21	7.342,43	20%

А

S

D

Total

company orders in one year by 97.55%, have not been able to meet the 100% target as set by the company.

10.800.00

42,589,00

110021,02

3%

4%

100%

3

4

103

Based on the explanation above, it can be seen that in the initial observation there was a waste problem that occurred at PT Y which resulted in the company not being able to meet the 100% order fulfillment target. Companies need improvements in the production process to be able to eliminate waste to support the company's mission of supporting increased productivity and elimination of waste.In this research lean was chosen because lean philosophy aims to reduce the waste that exists in the company by identifying and continually pursuing customer satisfaction. Lean philosophy is based on three basic rules including determining value, eliminating waste, and forming a smooth flow [2]. Lean manufacturing is a production philosophy that emphasizes the minimization of the use of resources (including time) used in activities carried out at the company, including identification and elimination of non-value-added activities in the process of design, production, supply chain management, and dealing with customers [3]

The product chosen in this study is the AA-series model because this product has the largest volume produced through

Table 1.	
Waste Code	

waste Code									
Code	Description								
W1	Defect Part Warping								
W2	Defect Electrical Error								
W3	WIP Inventory								
W4	Excessive movement on the component insert operator								
W5	High machine downtime								
W6	The process of repairing defect products								
W7	Circular material flow								
W8	Much time needed in WIP transfer time								
W9	Over inspection								
W10	Mark the PCB destination on the PWB								
	Table 2.								
	Root Causes of Waste Code								

	Root Causes of Waste Code
Code	Description
S1	Partial inspection
S2	No specific schedule for ICT machine maintenance
<b>S</b> 3	Production duration of each process is different
S4	The work station is not ergonomic
S5	The company do not have a preventive maintenance schedule
S6	There is no standard in handling defect product
<b>S</b> 7	Room layout that does not adjust the direction of the material
<b>S</b> 8	Capacity of hand truck for WIP transportation is small
S9	OQC process is not standard
S10	There is no PWB destination marking standard

the PCB process. Total AA-series production in one year reached 208.792 units with an average production per month of 17.399 units. The AA-series production process goes through several stages, namely WW, SPU, Injection, PCB, SA, RPA, and final assembly in the FA.

In this study the mapping of value added and non-value added activities with value stream mapping and process activity mapping. The lean manufacturing approach used for waste elimination is carried out with the Lean Assessment Matrix (LAM) developed by [4]. This method is a modification and integration of the House of Risk (HOR) and

*The 1st International Conference on Business and Engineering Management (IConBEM 2020)* February 1st 2020, Institut Teknologi Sepuluh Nopember, Surabaya, Indonesia

	Waste Type Weight Calculation Results												
F/T	0	Ι	D	М	Т	Р	W	SCORE	%				
0	0	0	0	0	0	0	0	0	0,%				
Ι	0	0	4	7	6	8	5	30	16,3%				
D	0	8	0	5	5	5	5	28	15,2%				
М	0	8	4	0	8	6	5	31	16,8%				
Т	0	10	4	10	0	6	4	34	18,5%				
Р	0	7	2	7	7	0	6	29	15,8%				
W	0	5	4	8	10	5	0	32	17,4%				
SCORE	0	38	18	37	36	30	25	184					
%	0 %	20,7 %	9,8 %	20,1 %	19,6 %	16,3 %	13,6 %	100 %					

Table 5.

Table 6. Severity Level of Waste Pesult

Code	Description	Severity Level of Waste	
W1	Defect Part Warping	8	
W2	Defect Electrical Error	8	
W3	WIP Inventory	6	
W4	Excessive movement on the component insert operator	7	
W5	High machine downtime	10	
W6	the process of repairing defect products	8	
W7	Circular material flow	8	
W8	Much time needed in WIP transfer time	9	
W9	Overinspection	2	
W10	Mark the PCB destination on the PWB	1	

Table 7.

	Determination of Occurrence Level of Root Source of Waste Result (RSOWR)								
Code	Description	Occurrence level of RSOWR							
S1	Partial inspection	4							
S2	No specific schedule for ICT machine maintenance	9							
S3	Production duration of each process is different	10							
S4	The work station is not ergonomic	10							
S5	The company do not have a preventive maintenance schedule	8							
S6	There is no standard in handling defect product	8							
<b>S</b> 7	Room layout that does not adjust the direction of the material	10							
<b>S</b> 8	Capacity of hand truck for WIP transportation is small	10							
S9	OQC process is not standard	10							
S10	There is no PWB destination marking standard	10							

Waste Relationship Matrix (WRM) that can comprehensively fulfill all stages of lean manufacturing implementation from waste and root causes of waste, determination of critical waste, alternative actions to eliminate root causes of waste and its priorities. With the combination of tools used in this study, it is expected to be able to solve the problems that occur at PT Y, especially at the PCB Production Department.

### II. RESEARCH METHODOLOGY

# A. Identification of Waste and Its Causes

Waste identification phase and its causes consist of observation and interviews, preparation of production process flowcharts, preparation of process activity mapping (PAM), compilation of current state value stream mapping, waste mapping, and root cause analysis of waste.

# B. Critical Waste Analysis

The critical waste analysis consists of determining the type of waste weight obtained from the results of the waste relationship matrix, determining the severity level of waste, determining the occurrence level of the root source of waste, and the mapping of Lean Matrix 1.

# C. Recommendations for Improvement

The design of improvement recommendations consists of several stages, namely the preparation of a number of alternative recommendations for improvement that form waste elimination actions (WEA). WEA will be the input of Lean Matrix 2. The preparation of Lean Matrix 2 requires several inputs, namely the calculation of the total effectiveness of WEA, determination of the degree of difficulty performing action determined by the company's experts, and calculation of the effectiveness to difficulty ratio. Lean matrix 2 will produce output in the form of rank of action priority that will be submitted to the company.

#### D. Conclusion and Suggestion

At this stage the conclusion of the research is carried out which answers the research objectives by considering the results of the research analysis. After conclusions are drawn, suggestions are made to the company and to further research.

#### III. RESEARCH RESULTS AND DISCUSSION

Value Stream Mapping (VSM)Value Stream Mapping is created based on [5]. From VSM in Figure 2, it can be identified that there is inventory waste in several production processes, including AV131 process, RG131 process, the SMT process, and the ICT process before the product is sent to the AMP Assy process. Other wastes that can be identified from VSM are defects that occur in the SMT process by 0.6% and in the solder process by 0.1%. The total cycle time of AAseries production is 9.3 minutes while the process lead time is 1.479 minutes. The changeover time in the value stream mapping indicates the different destinations (export

The 1<sup>st</sup> International Conference on Business and Engineering Management (IConBEM 2020) February 1st 2020, Institut Teknologi Sepuluh Nopember, Surabaya, Indonesia

								ole 14 Matrix 1							
					I	Root Sour	rce of Wa	iste							
Waste Type	Non Added Value Activity (Waste)	S1	S2	<b>S</b> 3	S4	S5	S6	S7	<b>S</b> 8	S9	S10	Waste Type Weight	Severity level of Waste	Aggregate Waste Number	Priority Rank of Waste
Defect	W1	9				3	3					15,2	8	10.214,40	8
Defect	W2		9		1	3	3					15,2	8	16.902,40	6
Inventory	W3		3	9					3	3		16,3	6	17.310,60	5
Motion	W4				9		3	1				16,8	7	14.582,40	7
W7-141	W5			3		9						17,4	10	17.748	4
Waiting	W6				1	9	9	1				17,4	8	22.828,80	3
<b>m</b>	W7				3			9	9			18,5	8	31.080	2
Transportation	W8			1	3			9	9			18,5	9	36.630	1
Unnecessary	W9						3			9		15,8	2	3.602,40	9
Process	W10										9	15,8	1	1.422	10
Occurrence leve Source of W		4	9	10	10	8	8	10	10	10	10				
Aggregate (	Cause	288	810	930	1.300	1.680	1.176	1.680	1.710	360	90				

Table 13

	Alternative Recommendations for Improvement	Deterr	nina
Code	Description	Code	
WEA1	Create ergonomic work station	WEA1	Cre
WEA2	Make preventive maintenance schedule	() En H	wo
WEA3	Make defect product handling standard		Ma
WEA4	Relayout PCB MI room in the direction of material	WEA2	ma sch
WEA5	Move the location of PCB MI between PCB SMT and FA		Ma
WEA6	Conduct training to improve product repair skills	WEA3	pro
WEA7	Increase material handling tools.		star
WEA8	Integrate OQC in every production process		Rel

destinations) of products that require production time to change product destinations related to the use of different material components

#### A. Process Activity Mapping (PAM)

Process Activity Mapping (PAM) is used to describe activities that occur in the PT Y PCB. PAM is made by describing the process, time, distance, manpower and type of activity (value added or not) [6]. The result of PAM can be seen in Table 1.

Based on Table 1, it is known that in the speaker production process the activity consist of necessary non value added activity (NNVA) of 47%, non value added activity (NVA) of 33%, and value added (VA) activity of 20 %. Based on Table 2, the most activities are operation (58%), inspection (20%), transportation (15%), delay (4%), and storage (3%). Transportation activities and delays are nonvalue added activities and must be reduced to increase productivity. Waste will then be analyzed in the Lean Assessment Matrix.

### B. Lean Assessment Matrix

#### 1) Lean Matrix 1

#### Waste Mapping a.

Based on observation and brainstorming with the company, identification of waste in PCB production process as follows: 1. Overproduction

There is no overproduction waste because the company production system is make to order.

#### 2. Defect

There are seven types of defect that found in PCB production process namely part warping, electrical error,

Table	12

Determination of Degree of Difficulty Performing Action									
Code	Description		Cost	Value					
WEA1	Create ergonomic work station	Rp	19.200.000,00	4					
WEA2	Make preventive maintenance schedule	Rp	2.880.000,00	3					
WEA3	Make defect product handling standard	Rp	-	3					
WEA4	Relayout PCB MI room in the direction of material	Rp	35.000.000,00	4					
WEA5	Move the location of PCB MI between PCB SMT and FA	Rp	550.000.000,00	5					
WEA6	Conduct training to improve product repair skills	Rp	2.000.000,00	3					
WEA7	Increase material handling tools.	Rp	750.000,00	3					
WEA8	Integrate OQC in every production process	Rp	-	3					

wrong polarity, poor solder, part missing, wrong part, Solder Bridge, part shifted, and part standing. The highest type of defect is part warping by 0.85%, then the electrical error is 0.1%, and wrong polarity by 0.02%. Part warping is a defect that is closely related to the quality of materials from suppliers and handling of this material. For electrical error, further analysis must be done and requires a longer handling time. 3. Inventory

From VSM, it can be seen that some PCB processes produce inventory in the form of WIP finish AV, WIP finish RG, and WIP finish MI. The average WIP storage time is 470 minutes or one production shift.

### 4. Motion

The results of observation and activity mapping on VSM and PAM show the existence of waste motion, which is excessive movement on the component insert operator. This is due to the position, the operator is on the right / left of a short conveyor containing material. This position causes the operator to turn around when retrieving and replacing the The 1<sup>st</sup> International Conference on Business and Engineering Management (IConBEM 2020) February 1st 2020, Institut Teknologi Sepuluh Nopember, Surabaya, Indonesia

				Table 18 Lean Matri						
				V	Vaste Elimin	ation Actic	n			
Waste Type	Root Source of Waste	WEA1	WEA2	WEA3	WEA4	WEA5	WEA6	WEA7	WEA8	Aggregate Cause
	<b>S</b> 3				1			1		930
	S4	9			3					1.300
Turner at time Waiting	S5		9				3			1.680
Transportation, Waiting,	S6			9			9			1.176
Inventory	S7				9	3				1.680
	<b>S</b> 8					9		3		1.710
	S9								9	360
Total Effectiveness of Wa Action m (TE		11.700	15.120	10.584	19.950	20.430	15.624	6.060	3.240	
Degree of difficulty performing action m (D <sub>m</sub> )		4	3	3	4	5	3	3	3	
Effectiveness to difficulty ratio (ETD <sub>m</sub> )		2.925	5.040	3.528	4.987,50	4.086	5.208	2.020	1.080	
Rank of action priority		6	2	5	3	4	1	7	8	

PCB from the conveyor. There are also operators who have f. Lean Matrix 1 Mapping Results difficulty reaching material components

5. Waiting

There are two kinds of waste waiting: high machine downtime and the process of repairing defect products.

6. Transportation

Circular material flow in the placement of PCB Assy on the production floor and WIP transfer time is longer because the production locations are on different floors (SMT and AI on the 1st floor: MI on the 2nd floor)

Unnecessary Process 7.

This waste include over inspection and mark the PCB destination on the Printed Wire Board (PWB) Further discussion regarding waste will follow Table 3

Analysis of Root Causes of Waste b.

The root causes of waste are analyzed using 5Why based on [7] and is shown in Table 4.

Calculation of Waste Type Weight

Waste type weight calculation is compiled from waste relationship matrix (WRM) questionnaire based on [8]. The questionnaire was answered by company experts. Waste type weight calculation results can be seen in Table 5. Based on Table 5, it can be seen that the highest percentage of waste is transportation (18.5%), waiting (17.4%), and motion (16.3%). For waste overproduction, as described in Section 3.3.1.1, no waste overproduction is found, so the value of waste type weight is 0.

d. Determination of Severity Level of Waste

Determination of severity level of waste is determined by the company's experts. The expected output from determining the severity level is a value on a scale of 1 to 10 and will then be used as a component in the preparation of lean matrix 1. The result of determination of severity level of waste can be seen in Table 6.

Determination of Occurrence Level of Root Source of e. Waste

Determination of the occurrence level aims to determine the likelihood or frequency of waste occurring on the production floor. Determination of the occurrence level of the root cause of waste is determined by the company's expert. The expected output from determining occurrence levels is a value on a scale of 1 to 10 and will then be used as a component in the compilation of Lean Matrix 1. The result of determination of occurrence level of root source of waste can be seen in Table 7.

The mapping result of Lean Matrix 1 can be seen in Table 8. The calculation step is following [4]. The result of Lean Matrix 1 are priority rank of waste (transportation, waiting, and motion) that need to be analyzed more in Lean Matrix 2.

# 2) Lean Matrix 2

Alternative Recommendations for Improvement a.

Alternative recommendations for improvement are made after knowing the type of waste that must be prioritized to be eliminated. It is obtained from discussions with relevant parties from company. Alternative recommendations for improvement can be seen in Table 9.

b. Determination of Degree of Difficulty Performing Action

The results of determination of degree of difficulty performing action by experts from the company can be seen in Table 10. The determination is by looking at work (projects) of similar improvements that have been carried out in the past and projecting on current improvement recommendations.

Lean Matrix 2 Mapping Results с.

The mapping result of Lean Matrix 2 can be seen in Table 11. The calculation step is following [4]. The result of Lean Matrix 2 are rank of action priority of waste elimination. From Table 11, the actions that were chosen: WEA6, WEA4, and WEA2.

# 3) Submission of Selected Recommendations based on Rank Action of Priority

Selected recommendations based on rank action priority:

a. WEA6: Conduct training to improve product repair skills Training priority that needs to be done is mechanical/electrical repairs carried out on the SMT and MI operator. Training is conducted to improve the operator's skills in repairing products that have defects, so that if a defect occurs, the operator can troubleshoot directly and minimize the number of defects that must be analyzed by the repairmen.

- In addition, training will also focus on following skills:
- 1. Understanding schematic diagrams
- 2. Mastering and understanding all types of PCB parts
- 3. Can operate a rework station
- 4. Mastering the standard specification of inspection PCB
- 5. Can use solder pots
- 6. Can touch up repair products

*The 1st International Conference on Business and Engineering Management (IConBEM 2020)* February 1st 2020, Institut Teknologi Sepuluh Nopember, Surabaya, Indonesia

This training will be conducted by PT Y internal employees so that it does not incur large costs. Costs incurred are the costs of providing modules, control cards, and progress reports on the training that will be conducted. The benefit prediction of this training subject to electrical error is Rp 145.124.392,00,0

b. WEA2: Make preventive maintenance schedule

Preventive maintenance schedules are made for the machines of all PCB sections. Four people (2 people from Production Engineering and 2 people from production) are responsible for carrying out preventive maintenance machines. The benefit prediction of this preventive maintenance schedule subject to corrective maintenance is Rp 26.437.700,00.

c. WEA4: Relayout PCB MI room in the direction of material

This change was made by adding goods entrances so that the WIP finish SMT was placed close to the insert material process. If WIP finish SMT has been placed near the material insert process, the direction of material flow is in the same direction and does not require high transportation. The benefit prediction of relayout PCB MI room subject to transportation is Rp 9.676.000,00.

# IV. CONCLUSION AND SUGGESTION

- A. Conclusion
- 1) Waste that gives the most significant influences in the production process in PCB section are transportation (W8 and W7), waiting (W6 and W5) and inventory (W3).
- 2) The root causes of waste problems that arise in the production process in PCB section include S3 (production duration of each process is different), S4 (The work station is not ergonomic), S5 (The company do not have a preventive maintenance schedule), S6 (There is no standard in handling defect product), S7 (Room layout that does not adjust the direction of the material), S8 (Capacity

of hand truck for WIP transportation is small), and S9 (OQC process is not standard).

3) Recommendations for the improvement of speaker production in the proposed PCB section include WEA6 (conduct training to improve product repair skills), WEA2 (make preventive maintenance schedule), and WEA4 (relayout PCB MI room in the direction of material).

# B. Suggestion

- 1) Calculate the results of improvements to the process cycle time after improvement.
- 2) The research phase is carried out until improvement implementation.

#### REFERENCES

- S. Nakajima, *TPM Development Program: Implementing Total Productive Maintenance*, 1st Editio. Portland Or.: Productivity Press, 1989.
- [2] J. P. Womack and D. T. Jones, "Lean Thinking: Banish Waste and Create Wealth in Your Corporation," J. Oper. Res. Soc., vol. 62, no. 1, pp. 1–2, 1997, doi: 10.1057/jors.2010.172.
- [3] J. F. Cox, J. H. Blackstone, and APICS--The Educational Society for Resource Management., APICS Dictionary, 9th ed. Athens: APICS, 1998.
- [4] P. D. Karningsih, A. T. Pangesti, and M. Suef, "Lean Assessment Matrix: A Proposed Supporting Tool for Lean Manufacturing Implementation," *IOP Conf. Ser. Mater. Sci. Eng.*, vol. 598, no. 1, 2019, doi: 10.1088/1757-899X/598/1/012082.
- [5] M. A. Nash and S. R. Poling, Mapping The Total Value Stream: A Comprehensive Guide for Production and Transactional Processes. New York: CRC Press, 2008.
- [6] R. A. Saputra and M. L. Singgih, "Perbaikan Proses Produksi Blender Menggunakan Pendekatan Lean Manufacturing Di Pt. Pmt," *Pros. Semin. Nas. Manaj. Teknol. XV*, pp. 1–9, 2012.
- [7] R. J. and K. C. Latino, Root cause analysis: improving performance for bottom-line results, 2nd Editio. Boca Raton, Florida: CRC Press, 2002.
- [8] I. A. Rawabdeh, "A Model for The Assessment of Waste in Job Shop Environments," *Int. J. Oper. Prod. Manag.*, vol. 25, no. 8, pp. 800– 822, 2005, doi: 10.1108/01443570510608619.